

Message

From: Powell, Greg [Powell.Greg@epa.gov]
Sent: 10/1/2018 4:08:29 PM
To: Moore, Gary [Moore.Gary@epa.gov]
CC: Singhvi, Raj [Singhvi.Raj@epa.gov]; Mickunas, Dave [Mickunas.Dave@epa.gov]; Blaze, Stephen [Blaze.Stephen@epa.gov]
Subject: RE: F.J. Doyle Salvage Stie

If you look for them you will probably find some of the isomers of dioxin. I'll forward to our chemists. Steve ,Dave and Raj any input?

Greg Powell
USEPA-ERT
Erlanger, KY Office
(859)594-6549 office
(513)607-1572 cell

"Facts do not cease to exist because they are ignored."

From: Moore, Gary
Sent: Monday, October 01, 2018 11:47 AM
To: Powell, Greg <Powell.Greg@epa.gov>
Subject: F.J. Doyle Salvage Stie

Greg:

Can you get this to the right person if not you?

We are going to be demolishing a building at a former PCB dismantling facility. They did do cutting and grinding on the transformers. It is a metal building with wood structures.

We are going to do the following: Asbestos Inspection – Required for Reno/Demo
We are planning on doing PCB wipe samples to include analysis for Aroclor 1268 (Galbestos?)
We are going to sample for lead paint

Question: Is there a need to include Dioxins/Furans for the wipe samples?

Thanks

Gary W. Moore (6SF-ER)
Federal On-Scene Coordinator
U.S EPA Region 6
1445 Ross Ave, Suite 1200
Dallas, TX 75202-2733
Cell: 214.789.1627
moore.gary@epa.gov